EXHIBIT B
SAMPLE STRUCTURAL INVENTORY AND APPRAISAL (SI&A) FORM

1/29/1990 TIN 514

UNDERWATER INSPECTION REPORT

TOWN (S) _____ BR NAME _____

		BRIDGE NO.	TEAM LEADER _____
193	1 2 1 2 0 1	DATE	DIVERS _____
493	2 4	EQUIP/ADD. INSP	TIME: ENTRY 1355
460	6	SUBST. COND.	EXIT 1605
461	6	CHAN. COND.	WEATHER Cloudy
697	2	SHAFT TYPE	WATER TEMP 33 degrees F
698	2	FOUNDATION	MAX DEPTH 20 FT
	RECOM. REPAIRS		VISIBILITY 2 FT
685	2 1 7 4 4		CURRENT 1/2 Knot +/-
686	2 1 2 4 4		INSP. SIGN _____

STREAMBED DESC. Semi hard mud and silt, with small stones and some debris.

COMMENTS/PROBLEMS/HAZARDS _____

INSPECTION REPORT Piers 3 and 4 are in satisfactory condition with minor deficiencies noted. Pier 2 footing was found to be cracked on its top and faces up to 1/8" wide, cracking under roadway expansion supports noted on all piers.